

DATE 1041Z 31 OCT 64

S E C R E T

| | | |
|---|-------|----|
| 1 | Conn | 9 |
| 2 | " | 10 |
| 3 | TOEPO | 11 |
| 4 | cc | 12 |
| 5 | OFFO | 13 |
| 6 | ORECH | 14 |
| 7 | | 15 |
| 8 | | 16 |

16

TO : DIRECTOR

25X1A

FROM : [REDACTED]

ACTION:

ROUTINE

INFO :

TOR: 1222Z 31 OCT 64

OSIA 1-20 E

IN 55372

To 25X1A

INFO [REDACTED]

CITE [REDACTED]

0373 25X1A
25X1A
25X1A

25X1A

HEREWITH [REDACTED] READOUTS FOR MSN NO C224C

OCT 31, 1964. BW 100 PERCENT EFFECTIVE. NO SYS 12 OR 13 ACTIVITY
NOTED.

PRE TAKE OFF:

0225Z BELOW 60M, BELOW 40M, EGT 325 OR LESS, RPM 75 PER CENT,
80 KIAS OR LESS, INVERTER NO 1 ON, AC GEN OUT, AUTO PILOT
DISENGAGED.

0225.5Z SAME EXCEPT A OK

0226Z SAME AS 0225Z

0227Z SAME AS 0225Z

0227.5Z SAME AS 0225Z

0228Z SAME AS 0225Z

REASON FOR ABOVE PROBABLY OXYGEN PRI ON FIRST CHIRP.

0229.5Z TAKE OFF:

BELLOW 60M, BELOW 40M, EGT 500-325 DEG C. RPM 75 PERCENT,
INVERTER 1 ON, AC GEN ON. AUTO PILOT DISENGAGED.

GROUP 1
EXCLUDED FROM AUTO-
DOWNGRADING
DOWNGRADING
EXCLUDED FROM AUTO-
DOWNGRADING

Approved For Release 2002/10/29 : CIA-RDP66B00664R00070095-3